


Last Modified: 07-05-2024	6.11:8.1.0	Doc ID: RM100000002JTUR
Model Year Start: 2024	Model: Land Cruiser	Prod Date Range: [02/2024 -]
Title: HORN: HORN: REMOVAL; 2024 MY Land Cruiser [02/2024 -]		

REMOVAL

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)




PROCEDURE		PART NAME CODE			
1	UPPER RADIATOR SUPPORT SEAL	53292A	-	-	-
2	HIGH PITCHED HORN ASSEMBLY	86510	-	-	-
3	LOW PITCHED HORN ASSEMBLY	86520	-	-	-

PROCEDURE

1. REMOVE UPPER RADIATOR SUPPORT SEAL

Click here [INFO](#)

2. REMOVE HIGH PITCHED HORN ASSEMBLY



3. REMOVE LOW PITCHED HORN ASSEMBLY

