



Bumper Cover Retainer Clip

75392-35220



Positions: Right

\$2.60 CAD

ADD TO CART



Fender Liner Clip

90467-07215



Positions: Right

MSRP \$2.12 CAD

\$1.58 CAD

ADD TO CART



Rocker Molding Retainer Clip

75868-60020



Notes: PARTS: Part included with lift gate trim.

Description: Rocker molding. Type 2.

MSRP \$13.05 CAD

\$9.63 CAD

ADD TO CART



Door Trim Panel Clip


90467-A0005



Notes: PARTS: Part included with lift gate trim.

\$2.56 CAD

ADD TO CART



Hook

66310-30011-C1



Description: With third row seat. Black. Lower section, driver side, lower. Lower section, passenger side, lower. Luggage compartment. rope type 2.

MSRP \$87.44 CAD

\$59.07 CAD

ADD TO CART



Upper Center Pillar Trim Clip

90467-10167



Positions: Left

Notes: PARTS: Part included with lower quarter trim.

MSRP \$1.90

\$1.55

ADD TO CART



Lower Center Pillar Trim Retainer Clip

90467-10161



Positions: Left

Notes: PARTS: Part included with lower quarter trim.

MSRP \$1.81

\$1.48

ADD TO CART



Protector Clip

90467-06165-C3



Toyota

Notes: PARTS: Part included with compartment box.

Description: Console & components. Without rear air outlets.

MSRP \$1.64

\$1.33

ADD TO CART



Bracket

63185-42020



Toyota


Description: With sunroof, without roof rack. To 5/2003, front. Upper.

Without sunroof japan built. front. With sunroof canada built. front.

MSRP \$4.88

\$3.99

ADD TO CART



Handle, Inside

69291-60060-C0



Toyota

Description: With power lift gate.

MSRP \$22.61

\$18.45

ADD TO CART



Upper Quarter Trim Clip

90467-10188



Toyota

Positions: Left

Notes: PARTS: Part included with upper center pillar trim. Part cannot be reused/reinstalled.

MSRP \$1.87

\$1.52

ADD TO CART



Power Outlet

85530-52010



Toyota

Positions: Right


Notes: PARTS: Part included with rear power outlet.

Description: Us built, 2021-24. Japan built. Console assembly & components. Without automatic transmission. Aux outlet. Lower section, passenger side. 2018-20 us built. Rear section. Socket.

MSRP \$55.40

\$45.20

[ADD TO CART](#)



12 Volt Accessory Power Outlet Cover

85535-78010



Toyota

Positions: Right


Notes: PARTS: Part included with rear power outlet.

Description: Without automatic transmission. Console assembly & components. Rear section. Lower section, passenger side.

MSRP \$13.65

\$11.15

[ADD TO CART](#)



Rear Power Outlet Bezel

85536-60140




Toyota

Positions: Right

MSRP \$15.37

\$12.54

[ADD TO CART](#)



Rear Quarter Trim Cap

62476-60020-C0



Toyota


Positions: Right

Description: Upper section.

MSRP \$18.04

\$14.73

[ADD TO CART](#)



Rear Quarter Trim Cap

62477-60020-C0



Toyota

Positions: Left

Description: Upper section.

MSRP \$18.04

\$14.73

[ADD TO CART](#)