

Last Modified: 07-05-2024	6.11:8.1.0	Doc ID: RM100000002I8V3
Model Year Start: 2024	Model: Land Cruiser	Prod Date Range: [02/2024 -]
Title: MIRROR (INT): INNER REAR VIEW MIRROR (w/ EC Mirror): REMOVAL; 2024 MY Land Cruiser [02/2024 -]		

REMOVAL

CAUTION / NOTICE / HINT


The necessary procedures (adjustment, calibration, initialization or registration) that must be performed after parts are removed and installed, or replaced during inner rear view mirror assembly removal/installation are shown below.




Necessary Procedure After Parts Removed/Installed/Replaced




REPLACED PART OR PERFORMED PROCEDURE	NECESSARY PROCEDURE	EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURES ARE NOT PERFORMED	LINK
Inner rear view mirror assembly	Register codes in the garage door opener system	Garage Door Opener System	INFO

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	NO. 2 FORWARD RECOGNITION COVER	86466E	INFO	-	-

PROCEDURE		PART NAME CODE			
2	NO. 1 FORWARD RECOGNITION COVER	86466D	INFO	-	-
3	INNER REAR VIEW MIRROR ASSEMBLY	87810	INFO	-	-

PROCEDURE


1. REMOVE NO. 2 FORWARD RECOGNITION COVER





	Click here INFO
---	---------------------------------

2. REMOVE NO. 1 FORWARD RECOGNITION COVER

	Click here INFO
---	---------------------------------

3. REMOVE INNER REAR VIEW MIRROR ASSEMBLY



	Tilt in this Direction		Remove in this Direction
	Screw		Connector

- (1) Detach the clamp and disconnect the connector.
- (2) Tilt the mirror surface down to the maximum tiltable position.
- (3) Using a T20 "TORX" socket wrench, remove the "TORX" screw.

- (4) Slide the inner rear view mirror assembly as shown in the illustration and remove the inner rear view mirror assembly.

